
APPENDIX I

Project Photo's

PHOTO 1



Existing Victor Road has narrow lanes and steep grades.

PHOTO 2



Near 100th Ave, the grades approach 8% and sight distance is poor.

PHOTO 3



Near Dimond Blvd., Existing curb & gutter, a narrow raised median and auxiliary lane.

PHOTO 4



Road with narrow unpaved shoulders.

PHOTO 5



The existing road is higher than the surrounding ground and ditches are adjacent to the travel lanes.

PHOTO 6



Drainage is conveyed by ditches and culvert system.

PHOTO 7



The existing pavement is in poor condition with numerous cracking.

PHOTO 8



Residential driveways on the West side of Victor Road.

PHOTO 9



Many utilities are present in the Victor Road corridor.

PHOTO 10



Detached pathway on East side of Victor Road.